
ASSEMBLY PARTS FULBAT

Assembly instructions

1. BOX CONTENT

- » 2x black mounting bars
- » 4x aluminium mounting clips
- » 4x screws + nuts Ø 8mm & spacers
- » 8x screws + nuts Ø 6mm & spacers



2. FOLDING THE MOUNTING CLIPS

- » Prepare the aluminium mounting clips for installation on the display.
- » Please fold them as indicated in each step.





- » Install the aluminium mounting clips around the display plastic tubes.
- » The mounting bars should be positioned as in the example.





4. FULBANK F2 INSTALLATION

» After installing the mounting bars, you can install the 3 Fulbank F2. You will need: 6x screws + 6x nuts Ø 6mm



5. FINAL RESULT

» You can start to charge your Lead-Acid and Lithium batteries.







